



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3913-041
Job Sheet 188729



Part No: D3913-041

Job Qty: 1 ea

Part Name: Long Basket Base Assembly, 350



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 1/15/19

Job Tracking No:

Due Date: 2/8/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D4020 REV A SHEET 4, D3913 REV D SHEETS 1,2,3,4,5 IPP Rev:A new issue DD 10.03.19 verified by:EC IPP Rev:B chg qty's DD 10.04.12 verified by:EC IPP REV:C 12.07.24 AS PER DWG REV.B DD VERF:EC IPP REV:D 13.08.21 DWG REV.C / ECN 13-624 DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		2/8/19	0.00	0.00	Start Up Large Fab-5		CC
100	Large Fab	1 pcs		2/8/19	0.00	10.00	Large Fab 1		CC
110	QC	1 pcs		2/8/19	0.00	0.00	QC9		CC
120	QC	1 pcs		2/8/19	0.00	0.00	QC5		CC
125	HandFinish	1 pcs		2/8/19	0.00	0.29	HandFinish2		DR 19/2/19
130	Powdercoat	1 pcs		2/8/19	0.00	0.93	Powdercoat2		BEB 19-02-19
135	Packaging	1 pcs		2/8/19	0.00	0.00	Packaging1		BEB 19-02-20
140	QC	1 pcs		2/8/19	0.00	0.00	QC3		19-2-20
150	HandFinish	1 pcs		2/8/19	0.00	0.50	HandFinish4		BEB 19-02-20
160	QC	1 pcs		2/8/19	0.00	0.00	QC5		FEB 21 2019 68
170	Packaging	1 pcs		2/8/19	0.00	0.00	Packaging3-2		BEB 19-02-20
180	QC21-SA	1 Ea		2/8/19	0.00	0.00	QC21		FEB 21 2019

Part Op 100 - 1- assemble ribs , weld as per dwg D3913 using DT9610A ***inspect before welding mesh*** 2-Cut D4020-1 base
Descriptions: mesh and tack weld all mesh on basket as per dwg D3913 and trim mesh to fit if necessary and trim to clear fasteners
holes on the ends 3- weld hinge (3) and Mounting brackets as per dwg D3913 ***take lid to locate hinge and bracket*** 4-
Weld D4672-1 blanking plates as per dwg
130 - 1- Plug holes and mask only interior of hinge (3) prior to powder coat
150 - Pick Kit

M138997 START: 2:15 TEMP: 325° FINISH: 2:45

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 pcs (2 ea)	90-Start up Operation	5143 339
D3913-1	Rib	1 pcs (1 ea)	90-Start up Operation	5148 464
D3913-15	Wide Handle Plate	1 pcs (1 ea)	90-Start up Operation	5143 390
D3913-3	Rib	1 pcs (1 ea)	90-Start up Operation	5145 057
D3913-7	Rib	2 Ea (2 ea)	90-Start up Operation	5143 685
D3913-9	Hinge Rib	1 Ea (1 ea)	90-Start up Operation	5148 608
D3916-041	Rib Assembly	2 Ea (2 ea)	90-Start up Operation	5149 947
D3916-5	Light Rib	3 Ea (3 ea)	90-Start up Operation	5144 313
D4016-1	Hinge Half, Base	3 pcs (3 ea)	90-Start up Operation	5115 309
D4017-7	Rib	3 pcs (3 ea)	90-Start up Operation	5143 925
D4017-9	Rib	2 pcs (2 ea)	90-Start up Operation	5148 935

008152

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date : _____	Sequence #: _____	QTY Affected : _____		MRB (QSI042)	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor		
			QC / QA Coordinator		
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					

D4020-11	End Mesh, Basket	2 pcs (2 ea)	90-Start up Operation	5150353
D4021-1	Handle Plate	3 pcs (3 ea)	90-Start up Operation	5143400
D4034-041	Aft Upper Rib Assembly	1 Ea (1 ea)	90-Start up Operation	5143301
D4034-043	Fwd Upper Rib Assembly	1 Ea (1 ea)	90-Start up Operation	5147371
D4672-1	Blanking Plate	2 pcs (2 ea)	90-Start up Operation	5145300
M304EX0.75-16F	Expanded Metal Flat SS	33 sf (33 ea)	90-Start up Operation	5125258
AN3-10A	Bolt	6 Ea (6 ea)	150-HandFinish	5132304-1
D2931	Bumper	2 pcs (2 ea)	150-HandFinish	F86435
MS20600-AD4W3	Cherry Rivet	2 Ea (2 ea)	150-HandFinish	5076007
MS21042L3	Nut	6 Ea (6 ea)	150-HandFinish	5094592
NAS1149F0332P	Washer	12 Ea (12 ea)	150-HandFinish	5134693-1
D4021-5	Blanking Plate	2 pcs (2 ea)	150-HandFinish	5144379
NAS1149FN832P	Washer	2 Ea (2 ea)	150-HandFinish	5136368-1

M. A. 008247

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D2581	2	63	0
	D3913-1	1	5	0
	D3913-15	1	25	0
	D3913-3	1	4	0
	D3913-7	2	16	0
	D3913-9	1	4	0
	D3916-041	2	10	0
	D3916-5	3	19	0
	D4016-1	3	168	0
	D4017-7	3	35	0
	D4017-9	2	10	0
	D4020-11	2	1	0
	D4021-1	3	50	0
	D4034-041	1	8	0
	D4034-043	1	7	0
	D4672-1	2	2	0
	M304EX0.75-16F	33	1,373	0
150-HandFinish	AN3-10A	6	201	0
	D2931	2	829	0
	D4021-5	2	32	0
	MS20600-AD4W3	2	241	0
	MS21042L3	6	2,340	0
	NAS1149F0332P	12	2,403	0
	NAS1149FN832P	2	3,365	0

Part Specifications

Specifications could not be found.

Plex 1/15/19 8:03 AM Dart.lajeunesse.marie



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S154115



Part: D3913-041

Job No: 188729

Serial No/Batch: S154115

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 02/15/19

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date : _____	Sequence #: _____	QTY Affected : _____		MRB (QSI042) _____	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details: _____					